

~~SECRET~~

DM

IDEA

16.7

IN: 56187

25X1A6c

*Handwritten signature*  
05A-15

~~SECRET~~ 062305Z CITE [REDACTED] 2058

CITE

25X1A6c PRIORITY [REDACTED]

IDEALIST AVIONICS

25X1A2g

1. PRELIMINARY ANALYSIS OF 6 SEPT [REDACTED] TEST FLIGHT INDICATES SUCCESSFUL PERFORMANCE OF SYSTEM 6A

2. AT PREFLIGHT TAG AND TMT SIGNALS FROM SYSTEM 13 WERE NOT GETTING TO THE RECORDER. ONE CUT CABLE AND ONE DISCONNECTED CABLE WERE RESPONSIBLE. NO TIME AT PREFLIGHT TO TAKE CORRECTIVE ACTION.

3. SYSTEM 13 FAILED EARLY IN FLIGHT. POST FLIGHT QUICK LOOK INDICATES H.V. POWER SUPPLY FAILURE.

4. TWO MC RECORDERS WERE INSTALLED AND OPERATED DURING THE FLIGHT. TAPES WILL BE ANALYZED AS SOON AS POSSIBLE.

~~SECRET~~ TOR: 062320Z OCT 67

~~SECRET~~

GROUP 3  
EXCLUDED FROM AUTOMATIC  
DOWNGRADING AND  
DECLASSIFICATION